


FIGURE 7.2



**KEY**

- A = Doctors (See Figure 7.3)
- B = Hospital (See Figure 7.3)
- C = Aged Persons Home
- D = Swinford Primary School
- E = Luttenworth College (See Figure 7.3)
- F = Farm Shop
- G = Post Office (See Figure 7.3)
- H = Swinford Village Hall
- I = St. Thomas' Church
- J = All Saints Church
- K = 'Chequers' Public House
- L = 'Cherry Tree' Public House
- M = 'The White Swan' Public House
- N = 'Ken Marriot' Sports Centre (See Figure 7.3)
- O = M1 Junction 18 (Southbound) (See Figure 7.3)
- P = M1 Junction 20 (Northbound) (See Figure 7.3)
- Q = M6 Junction 1 (Westbound) (See Figure 7.3)
- R = A14 Junction 1 (Eastbound) (See Figure 7.3)

R = A14 Junction 1 (Eastbound) (See Figure 7.3)

Q = M6 Junction 1 (Westbound) (See Figure 7.3)

P = M1 Junction 20 (Northbound) (See Figure 7.3)

O = M1 Junction 18 (Southbound) (See Figure 7.3)

N = 'Ken Marriot' Sports Centre (See Figure 7.3)

M = 'The White Swan' Public House

L = 'Cherry Tree' Public House

K = 'Chequers' Public House

J = All Saints Church

I = St. Thomas' Church

H = Swinford Village Hall

G = Post Office (See Figure 7.3)

F = Farm Shop

E = Luttenworth College (See Figure 7.3)

D = Swinford Primary School

C = Aged Persons Home

B = Hospital (See Figure 7.3)

A = Doctors (See Figure 7.3)

- Local Vehicle Traveller Utility Routes
- Vulnerable User Utility Routes
- Vulnerable User Recreational Routes
- - - Footpaths
- - - X6 Bridleways

**NOTES**

1. For locations of key community facilities in the wider area see Figure 7.3.



Project: M1 JUNCTION 19 IMPROVEMENT ENVIRONMENTAL STATEMENT VOLUME 2  
 Chapter 7: EFFECTS ON ALL TRAVELLERS BASELINE CONDITIONS ASSESSED ROUTES - LOCAL AREA

Client	0	ALD 00	Final Issue	LO	CB	SH	TW
Scale	1:5000 @ A3			Client	Client	Client	Client
Drawing number	FIGURE 7.2						
Page	0						

Reproduced by permission of Ordnance Survey on behalf of HMSO. © Crown copyright and database right 2010. All rights reserved. Ordnance Survey Licence number: 1000189282.